



2 POLES






CABLE INDICATION




LIGHT BLUE (Art. X974 - X977):
250/400V

REBBLE GREY (Art. X975-X978):
50-120V

RIGID $S = 0,2 \div 1 \text{ mm}^2$
STRANDED $S = 0,22 \div 1 \text{ mm}^2$
STRANDED WITH FERRING $S = 0,22 \div 0,75 \text{ mm}^2$




CONNECTION DISTRIBUTOR



FORCE

NO

FORCE



NO

FORCE


NO

FORCE




OK

$R_{min} \geq 4xD$

OK



NO



DISCONNECTION

- 1
- 2
- 3
- 4

Diagram illustrating the removal of the cap and the insertion of the rod into the handle.

1. Remove the cap from the handle.

2. Insert the rod into the handle.



إذا كان هناك خطر من الغمر لفترة طويلة، يستحسن استخدام وصلات مناسبة (مثل أداة عازلة). AR